



Runways

18/36: 2670 x 50 (ASPH-P)

Coordinates

Latitude 42-41-27.283N
Longitude 073-34-46.416W

Communications

CTAF/U 122.7

Navigation

Elevation 440
NM from City 06 SE
Instr Approach NONE

Owner/Manager

Owner DU THIS DU THAT INC
Manager MR GEORGE M DU JACK JR
PO BOX 3095

Services

Fuel
Airframe Repairs
Engine

TROY NY 12181
Phone 286-1376 (airport)
Fax 286-1376
E-mail
Web site

Attended UNATNDD
Airline Airport NO
Transportation
Food
Lodging

FBO (Location)

MR GEORGE M DU JACK JR
286-1376 (airport)

Remarks

DEER & BIRDS ON & INVOF ARPT.
TRANSIENT ACRFT SHOULD CALL AMGR
FOR FIELD CONDITION PRIOR TO ARRIVAL.
RWY 18/36 HAS CRACKES, LOOSE ROCKS &
VEGETATION THROUGH CRACKS.
SURROUNDING TERRAINS SLOPES DOWN
TO RWY. ARRVL RWY 18 MAINTAIN
SUFFICIENT HEIGHT ABOVE RESIDENTIAL
AREA TO PREVENT HIGH POWER USAGE OR
LOW ALT.